


- 100 - SCH 04

FIG. 1



09/937831

100S 932 8 S OTPT9P9C9101A

FIG. 2






FIG. 3




09/937831

FIG. 4



09/937831

FIG. 4



1028 928 8 5 0774794 014

FIG. 4





FIG. 5



◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGIONS 6a-6c

◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGIONS 6a-6c

◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6c

◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6c


◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6b

◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6b

◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6a


◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6a

FIG. 5




- : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGIONS 6a-6c
- : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGIONS 6a-6c
- ◻ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6c
- ◻ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6c
- ◻ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6b
- ◻ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6b
- ◻ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6a
- ◻ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6a

FIG. 5



- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGIONS 6a-6c
- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGIONS 6a-6c
- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6c
- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6c
- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6b
- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6b
- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY SOLID LINE THAT HAS MOVED PAST REGION 6a
- ◎ : BEAM OF LIGHT INDICATED IN FIG. 4 BY BROKEN LINE THAT HAS MOVED PAST REGION 6a

FIG. 6



09/937831

100S 932 8 S 09/937831A

FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11 PRIOR ART




FIG. 12 PRIOR ART






FIG. 13 PRIOR ART




FIG. 14 PRIOR ART

